

PowerStudio Changelog



Index

4.0.12 -> 4.0.13.....	3
4.0.13 -> 4.0.14.....	3
4.0.14 -> 4.15.4.....	4
4.15.4 -> 4.16.3.....	4
4.16.3 -> 4.17.19.....	5
4.17.9 -> 4.19.4.....	5
4.19.4 -> 4.21.0.....	6
4.21.0 -> 4.22.0.....	6
4.22.0 -> 4.23.0.....	7
4.23.0 -> 4.24.0.....	7
4.24.0 -> 4.25.0.....	8
4.25.0 -> 4.26.0.....	8
4.26.0 -> 4.28.0.....	9
4.28.0 -> 4.29.0.....	9



4.0.12 -> 4.0.13

Features

Direct access to screens, reports or devices directly from a specified URL is allowed (scadaId?,reportId?, deviceId?)

Drivers

DHC 96 + DHC 96 CPM

Line-EDS

CEM C6 MID

CVM C4

AFQm

4.0.13 -> 4.0.14

Features

Counter function added to line-M-4IO modules

Drivers

Line CVM D32

Line-M-4IOA

Bugfixes

Led "slaves" in line-EDS



4.0.14 -> 4.15.4

In this version, the version numbering is changed. The first digit corresponds to the PowerStudio version, the second digit is incremented if new features or drivers are added. The third digit is incremented by bugfixes.

Features

WIFI parameter configuration added to line-EDS

Bugfixes

Errors in CVM C4 parameter reading corrected

Errors in AFQm parameter reading corrected

Errors line-M-4IOT parameter saving corrected

4.15.4 -> 4.16.3

Features

The IP assigned by DHCP in the line-EDS is displayed in the websetup

Drivers

RGU-100B

Bugfixes

Gateway reading error during line-EDS startup corrected



4.16.3 -> 4.17.19

Bugfixes

Bug in writing outputs of line-M-4IOA modules fixed

Error in time synchronization via NTP servers corrected

Communication errors via the line bus corrected

Bug in the display of VL1 and VL2 history in CVM E3 Mini WiEth fixed

4.17.9 -> 4.19.4

Drivers

Line-TCPRS1+

Line-M-3G

AFQm over RS485

Bugfixes

Error when registering temperature sensor TH-DG-int corrected



4.19.4 -> 4.21.0

[Features](#)

DynDNS functionality included in line-M-3G

[Drivers](#)

Line-M-20i

[Bugfixes](#)

Active Mode Bridge did not work correctly with the line-M-3G module

Counter values of line-M-4IO modules are saved as incremental

4.21.0 -> 4.22.0

[Features](#)

SMS sending from M-3G line is included

[Drivers](#)

DHC 96 CPM 1500

[Bugfixes](#)

Bug in ID verification in CEM C21/31 DS MID fixed

Bug in History saving in PowerNET fixed

Error in current leakage reading in RECMAX CVM corrected

Bug when accessing to device parameters in READWATT fixed



4.22.0 -> 4.23.0

Features

Assigning inputs and outputs names to all modules of the line range allowed

Drivers

Line-M-8I6O

4.23.0 -> 4.24.0

Features

Cadence time is increased to 15 minutes

Drivers

DHC 96 Vdc

Bugfixes

Bug in CVM D32 factors fixed

Bug when counters of line-M-4IO modules reached their maximum value fixed

Bug in AFQm factors fixed



4.24.0 -> 4.25.0

Features

5-minute recording time is enabled on the CVM B150 when connected to a PC

Measuring devices are separated into 2 tabs in the Editor

Bugfixes

Bug in the device alarm configuration dialog fixed

Bug when uploading A1500 quality events to a higher engine fixed

4.25.0 -> 4.26.0

Features

Line-M-3G can be configured without SIM card user and password

Drivers

TCPRS1+

CEM C12



4.26.0 -> 4.28.0

[Features](#)

In the line-EDS range, it is possible to choose whether the limits are counted per variables or per devices

[Drivers](#)

CVM C11

[Bugfixes](#)

Bug in line-M-4IOA analogue input factors fixed

Error when generating reports from HTLM5 viewer corrected

Error when saving of energies in the CEM C12 as incremental corrected

Error when forcing digital outputs in the expansion modules of the A1500 corrected

4.28.0 -> 4.29.0

[Features](#)

Added features in the DHC-96 CPM driver

[Bugfixes](#)

Error when saving data from a CVM-E3-MINI in database corrected.

Bugs in CVM-C11 driver fixed.

